





## 0055 - R134a PRIMARY SEAL CAPS & VALVE CORES ASSORTMENT

<p><b>5044</b> UNIVERSAL R12-R134a VALVE CORE</p>  <p>11</p>	<p><b>5045</b> GM HIGH FLOW LARGE BORE R12-R134a VALVE CORE</p>  <p>4</p>	<p><b>5102</b> HIGH FLOW R12-R134a JRA VALVE CORE</p>  <p>4</p>	<p><b>5103</b> STV/ POA/ VIR OIL BLEED LOW R134a PRESSURE VALVE CORE</p>  <p>4</p>	<p><b>5104</b> EATON 13MM SSV HIGH FLOW R134a VALVE CORE</p>  <p>2</p>	<p><b>5105</b> EATON 16MM SSV HIGH FLOW R134a VALVE CORE</p>  <p>2</p>
<p><b>5490</b> HYUNDAI / KIA 1994 - PRESENT R134a VALVE CORE</p>  <p>1</p>	<p><b>5491</b> EUROPEAN LARGE BORE R134a VALVE CORE</p>  <p>1</p>	<p><b>5042</b> R134a RED HIGH SIDE CAP</p>  <p>5</p>		<p><b>5043</b> R134a BLUE LOW SIDE CAP</p>  <p>5</p>	
<p><b>MT0061-5</b> R134a BLUE LOW SIDE CAP M8 - 1.0</p>  <p>1 (5 PK)</p>	<p><b>MT0062-5</b> R134a BLACK LOW SIDE CAP M8 - 1.0</p>  <p>1 (5 PK)</p>	<p><b>MT0068-5</b> R134a BLACK HIGH SIDE CAP M10 - 0.75</p>  <p>1 (5 PK)</p>	<p><b>MT0069-5</b> R134a RED HIGH SIDE CAP M8 - 1.0</p>  <p>1 (5 PK)</p>	<p><b>MT0106-5</b> R134a BLACK PRIMARY HIGH SIDE CAP M8 - 1.0</p>  <p>1 (5 PK)</p>	
<p><b>MT0310-5</b> R134a LIGHT BLUE LOW SIDE CAP M9 - 1.0</p>  <p>1 (5 PK)</p>	<p><b>MT0311-5</b> R134a LIGHT BLUE HIGH SIDE CAP M10 - 1.0</p>  <p>1 (5 PK)</p>			<p><b>MT0348-10</b> R134a BLACK LOW SIDE CAP M8 - 1.0</p>  <p>1 (10 PK)</p>	